



Greenslade & Company, Inc.




Dimensional Calibration & Innovative Gage Design

2234 Wenneca Avenue, Fort Worth, Texas 76102 U.S.A

817-870-8888, 817-870-9199 Facsimile

sales@greensladeandcompany.com

www.greensladeandcompany.com



External 6 Lobe Inspection

1. Slide the 6 Lobe head between the lobes in the gage's first position to the left until it stops.

For acceptance, the straight lobe portion of the 6 Lobe head must extend above the minimum lobe height step.

2. Slide the 6 Lobe head into the center hole until it stops.

For acceptance, the head must completely enter the hole until it stops on the top of the washer surface.

3. Slide the 6 Lobe head into the hole on the right until it stops.

For acceptance, the top of the bolt head must **NOT** protrude above the gage's top surface.